

**AIRMARK OVERHAUL, INC.**

6001 NW 29th AVE

FT. LAUDERDALE, FL. 33309

Customer No. ULM001

Telephone 954/970-3200

FAA Repair Station JL4R288M

Bill To:**ERIC ULMER**

6412 MALONEY AVE.

HOPKINS, MN 55343

USA

Ship To:**ERIC ULMER**

ERIC ULMER

ADOLF FREDRIKS KYRKOGATA 15

5TR, STOCKHOLM, 111 37 SWEDEN

Date			Ship Via		F.O.B.		Terms			
Jun 17,2013			T.B.A.				C.O.D.			
Customer Order Number			Order Date	Salesperson		Contact			Our Order No.	
VERBAL			Mar 07,2013	DW					43568	
Quantity			Part Number / Description				CD	Tax	U.Price	Amount
Req.	Ship.	B.O.								
1	1	0	PARTS PARTS Part Number : E185-8 / ENGINE, TCM Serial Number : 20428-D-0-8 Manufacturer : TELEDYNE OVERHAULED, TESTED AND CERTIFIED OVERHAULED WITH FACTORY NEW CYLINDERS AND THE FOLLOWING ACCESSORIES: MAGNETOS, MAGNETO HARNESS, SPARK PLUGS, STARTER, FUEL PUMP AND THE CARBURETOR. AIRMARK ENGINES, INC. 59-1640131 dba AIRMARK OVERHAUL, INC. The Export Classification Control Number (ECCN) for this product is 9A991(d) "Aircraft parts and components,n.e.s."United States law prohibits disposition of these commodities to U.S. sanctioned countries unless otherwise authorized by the United States.See<http://www.treas.gov>(OFAC Sanctions)and also<http: //www.bis.doc.gov>. Recipient of these goods agrees to comply with all export regulations governing the transfer, sale,lease or use of these goods.Diversion contrary to U.S. law is prohibited. License Symbol: NLR(C33) Schedule B: 9801.10.0000					Y	20465.0000	20465.00